TO: Dick Coulomb

              HID Global

              Irvine, CA 92618-2215
              Bethesda, Maryland 20814

FROM: Chi Hickey on behalf of the FIPS201 Evaluation Program

DATE: 04/17/2014

RE: **Approval of Products/Services for Listing on the GSA APL**

Office of Management and Budget (OMB) issued M-06-18 that requires Federal Agencies to procure only qualified products and services listed on the GSA Approved Products List (APL) when implementing HSPD-12 into their environment. Procurement of approved products and services facilitates the government-wide objective of a federated and interoperable ICAM segment architecture, and ensures compliance, consistency and alignment of commercially-available products and services with the requirements and functional needs of government ICAM implementer.

Accordingly, the FIPS 201 Evaluation Program (Program) is very pleased to inform you that the following product/service has passed testing against all applicable Testing Requirements. Please see the attached document that summarizes the specific parameters of the approval (e.g., product/service profile, what your product/service was tested with). Your product/service will now be listed on the APL as shown below. If there are any errors in the listing information, please notify me within five (5) business days of receiving this letter.

1   Category-PACS PIV Reader

Case File Number APL-140015

- (APL#10004)

  - pivCLASS RK40 Contactless reader

1.1   Product/Service Information

Organization Name:	HID Global
Name of Product or Service:	pivCLASS RK40 Contactless Reader
Part Number:	921NHR
Hardware Version:	REV.E
Software Version:	N/A
Firmware Version:	VAS00139
Authentication Support	Single Factor (CAK)

1.2   Restrictions:

The end to end solution components used to test the compliance of the approved solution are listed below.

- PACS Infrastructure: (APL# 10001)
  - Software House C*Cure 9000 Release 2.20 P1
  - iSTAR Edge Controller w/ POE

- Validation System   (APL# 10002)
  - pivCLASS Registration Engine (CCURE 9000)
  - pivCLASS Certificate Manager
  - pivCLASS Reader Services
  - pivCLASS IDPublisher
  - pivCLASS Authentication Module

- PACS Infrastructure   (APL# 10009)
  - Brivo ACS-Aparato BA50 –Brivo Aparato OnSite Appliance
  - Brivo ACS 5000-A-F Series Onsite
  - Brivo Two Reader Expansion Daughter Board
  - Brivo IP Door Controller for Aparato
  - Brivo IP Door Controller FIPS module License

- Validation System   (APL# 10010)
  - HID pivCLASS Registration Engine (MultiPACS)
  - HID pivCLASS MultiPACS Console
  - HID pivCLASS MultiPACS connector for Brivo Aparato
  - HID pivCLASS Registration Engine (Brivo Aparato)
  - HID pivCLASS Certificate Manager
  - HID pivCLASS Reader Services
  - HID pivCLASS IDPublisher
  - HID pivCLASS Authentication Module

- PACS Infrastructure: (APL# 10011)
  - Software House C*Cure 800 Release 10.3.0
  - iSTAR Edge Controller w/ POE

- Validation System   (APL# 10012)
  - pivCLASS Registration Engine (CCURE800)
  - pivCLASS Certificate Manager
  - pivCLASS Reader Services
  - pivCLASS IDPublisher
  - pivCLASS Authentication Module

- PACS Infrastructure   (APL# 10013)
  - Velocity 3.5 Security Management System
  - Hirsch Panel

- Validation System   (APL# 10014)
  - pivCLASS Registration Engine (Hirsch-Identive Velocity)
  - pivCLASS Certificate Manager
  - pivCLASS Reader Services
  - pivCLASS IDPublisher
  - pivCLASS Authentication Module

Approval of the above product/service indicates your cooperation with the Program and successful testing against a rigorous, comprehensive set of functional requirements derived from government-wide specifications. Testing included positive and negative test cases, and threat vectors.

Given the strategic government-wide importance of the APL, the scope and extent of testing performed on your product/service, and the rigor of that testing, the Program would like to acknowledge the noteworthiness of the approval and listing. Your product/service will now be available to all Federal Agencies for procurement.

Please note that continued listing on the APL requires ongoing conformance to all applicable requirements, including requirements added or amended over time. A listed product/service can become non-conformant for various reasons including but not limited to:

- Failure to pass testing against new and revised requirements before the effective date of the new/revised requirements.

- Problems discovered in your listed product/service (or class of product/service) are not addressed within time frames specified by the Program.

Refer to applicable Agreements and Program documents for specific details regarding ongoing compliance including severity levels and remediation time frames. Listed products and services that fall out of conformance will be removed from the APL and added to the Removed Products List (RPL).

If you have any questions, please feel free to contact me.

Chi Hickey
Chi Hickey
GSA OGP
202-501-1881 (desk)
202-617-6883 (cell)
Chi.Hickey@gsa.gov